

4T65E Manual Shift Automatic (Tap Shift) Valve Body Gaskets

In the 2004 model year, General Motors started to offer a manual shift automatic option, also known as tap shift, on certain models. This option requires a different set of valve body gaskets than the traditional 4T65E units.

CORTECO is pleased to announce the addition of the valve body gaskets required for the manual shift automatics to all TransTec® brand 4T65E kits with a date code of 3/25/10 and later. These gaskets are found in sub kit 4781 and are the same gaskets that are unique to Volvo applications that have a 4T65E transmission.



A Division of Freudenberg-NOK